

GoTo Worktables | Cleaning Instructions



POWDER COAT FINISH AND LAMINATE TOPS

1. Clean with a soft damp cloth and mild detergent.
2. Wipe dry.

IMPORTANT

Avoid using abrasive cleaners, chemical solvents, strong detergents, cleaners with bleach, and furniture polish.